Subject: Re: 7Pi Build 2014

Posted by Wayne Parham on Mon, 06 Oct 2014 19:30:35 GMT

View Forum Message <> Reply to Message

I think I see the problem. If this is it, I owe you a big old bottle of your favorite adult beverage.

Look at the crossover photo you sent earlier. See the area I've circled in red:

If those resistors are touching the land in the circled area, then the tweeter circuit is shorted and it has no output. Pull the resistors up away from there - so they touch only the line going to the (+) lug - and see if you don't have nice tweeter output.

If that's it, I apologize not only for sending the boards out that way but also for not looking closer at the photo you posted. I have someone building boards for me, and they may not have tested their work as thouroughly as we should have.

And let me know what you drink.

File Attachments

1) bad_xo.jpg, downloaded 8933 times