
Subject: Re: Four Pi Frequency Response
Posted by [timhowell01](#) on Sun, 08 Mar 2015 04:17:14 GMT
[View Forum Message](#) <> [Reply to Message](#)

I'll try another measurement tomorrow with a different microphone (still not calibrated, but may give a better result) and see what that shows.

Could there be a problem with the cabinet causing the rolloff? The only thing I can think of is that I didn't use gaskets around the woofer and the waveguide, but I think they're pretty well sealed even so. If they're not, would that be sufficient to explain the drop off?

I built the crossovers myself, but I quadruple checked them, so I don't think that is the problem.

--TWH
