

---

Subject: Re: 4 pi speakers + 3 pi subwoofers, pics & measurements

Posted by [tom-m](#) on Wed, 03 Jun 2015 23:12:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Wayne,

In his crossover, the coils are not positioned on the board in the recommended way. Would this be the cause of his issue?

Tom

---