

---

Subject: Re: Counterpoint SA 1000

Posted by [Manualblock](#) on Fri, 31 Dec 2004 16:13:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The Dynaco's do that with bad filter and coupling caps. My 2c from experience. The Lytics also in the power supply.

---