
Subject: Grid stoppers- No change

Posted by [TubeCraft](#) on Thu, 13 Jan 2005 12:07:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

Put 1k right up against the pin. No effect. I guess I'll slap together a breadboard with a new socket and try it out. It's gotta be the socket/connection. Unless the laws of physics are temporarily suspended in the driver section of my amp....
