

---

Subject: Re: Why?

Posted by [Manualblock](#) on Wed, 26 Jan 2005 14:48:05 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks for the Link AK; So in the parafeed you need to replace an expensive transformer with an expensive large choke; and in PP the mis-match unbalanced DC causes frequency imbalance; requireing much higher HT and therefor larger transformer.. Is that correct?Thanks J.R.

---