
Subject: Re: Build Thread: 2Pi Towers, 6Pi Corner horns (and possibly a sub and center)

Posted by [joshua43214](#) on Tue, 22 May 2018 16:47:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

Here are the pics from the 6Pi parts.

Those with sensitive stomachs beware...

The Crossovers got hammered to death by one of the Compression drivers. Wayne asked me to send them back for assessment, and UPS managed to sit on them for so long they didn't get back to him til late last week.

They look even worse in person, even the resistors got bent and almost ripped off the boards.

The Delta 10 is about 1/4" out of round

and the Delta 12 is bent over 1/4" out of flat.

Wayne also asked me to send the compression driver back since it was probably the hammer that caused the problems.

All in all, it was a very sad day.

Hoping the replacements arrive before the 6Pi's are complete, the race is on

File Attachments

- 1) [Sploded_Xover.jpg](#), downloaded 3513 times
 - 2) [Bent_Delta12.jpg](#), downloaded 3534 times
 - 3) [Bent_Delta10.jpg](#), downloaded 3547 times
-