

---

Subject: Figured it out!

Posted by [hurdy\\_gurdyman](#) on Tue, 06 Sep 2005 19:24:03 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I got the old Scott fixed. Turns out that a 68 ohm resistor in the negative feedback circuit was open. Everything sounds great now.Dave

---