

---

Subject: actually...

Posted by [hurdy\\_gurdyman](#) on Thu, 08 Sep 2005 12:38:10 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Pin 8 was hooked to pin 1, but with all the experimenting going on, it was un-hooked when the cathode resistors were installed.

---