

---

Subject: Re: 4 Pi Crossover

Posted by [Wayne Parham](#) on Fri, 05 Feb 2021 14:55:26 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'll send plans via email.

I would suggest swapping the midwoofer, then the tweeter compression driver and then the crossover board. Make sure you are focused on the right thing.

If it turns out it's the crossover, I'd replace the resistors first, followed by the capacitors. I can't imagine the coils going bad but if all else fails, I guess you could try swapping them too. But I'm sure you will have found your culprit long before you get to that point.

---