

---

Subject: Re: What problem does that fix?

Posted by [FredT](#) on Tue, 12 Oct 2004 18:59:25 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Some believe panel resonances translate to vibration, which could compromise the player's ability to accurately reproduce low-level detail. For example, Marantz used to offer the standard CD67 player and an upgrade version, the CD67-SE. In addition to better quality caps in the audio section, the CD67-SE had a double bottom chassis plus a cross brace over the top for vibration control. But you may be correct, in which case I am the one with a loose screw, having frittered away three whole dollars of my hard earned money.

---