

---

Subject: Re: Tube amp noise problem  
Posted by [Paul C.](#) on Sun, 22 Jan 2006 02:28:38 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

He says the chassis has only four 6L6 tubes. The rectifier is solid state.

---