
Subject: Re: 8 years later

Posted by [Wayne Parham](#) on Wed, 26 Jan 2022 22:54:30 GMT

[View Forum Message](#) <> [Reply to Message](#)

It's definitely odd that both act the same way.

But regardless, let's just step through the troubleshooting procedure. Using an ohmmeter, measure across the following terminals and report back what you see:

1. Measure from IN- to 2- and find zero ohms.
 2. Measure from IN+ to 2+ and find 4.5 ohms.
 3. Measure from 2+ to 2- and find 8 ohms.
-