

---

Subject: Re: Cornerhorns - what corners are "good enough"?

Posted by [rvsixer](#) on Thu, 14 Apr 2022 15:32:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

My apologies, it appears I likely used the term acoustic center incorrectly. My question was directed at the LP to R/L mains separation "triangle" (viewed as if your were looking down from the ceiling).

However I just ran the actual numbers based on my room setup, and there is only a 0.5 degree angular difference to the LP among the 6pi drivers. So basically of no concern.

---