
Subject: Re: My 4 Pi Build

Posted by [Unity_Coupled](#) on Sun, 15 Oct 2023 04:18:24 GMT

[View Forum Message](#) <> [Reply to Message](#)

I may have goofed on the 1/4-20 screws and bought ones that are too long, since they are only partly threaded. It looks like the 2" ones are going to bottom out before applying sufficient clamping force to the frame of the woofer, since it will be mounted flush with the baffle. I've re-ordered the screws, this time in 1.5" length. (part no. 91251A546)

Just thought I'd put this out there in case anyone was going to copy my McMaster order.
