Subject: Re: Where to get JBL 2226 Dustcap Replaced? Posted by Wayne Parham on Tue, 05 Dec 2023 01:11:16 GMT View Forum Message <> Reply to Message

So glad to hear that there is a repair center close to you!

As for the crossover, I think possibly one of the wires that connects the coil to the board is touching a land that it shouldn't. If it became dislodged, then it's possible that happened during re-attachment.

Can you take a photo of the crossover and send it to me via email or post it here on this thread?

