

---

Subject: Re: PS Transformers

Posted by [Manualblock](#) on Sat, 29 Jul 2006 11:58:25 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sorry; I assumed you were using the rated spec of the transformer and wall voltage. To measure off-load voltage you connect the primaries to the AC line input then use a voltmeter on the two legs of the secondaries right?

---