

---

Subject: Re: New Transformer

Posted by [Manualblock](#) on Mon, 07 Aug 2006 13:01:22 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I had a problem with that voltage also; and the trans weighs about 5 lbs. But this comes out of a Lafayette receiver so it may have used a voltage doubler. Here's a better description. The primary side has 7 tabs. Looking from left to right they are marked E 6V 2.3A (This one is connected across the trans to the other secondary) 6v.6a tab. 117v/100v/0v Tabs 4&5&6 The last tab is blank; no writing. On the sec side; 6 tabs; starting from left to right; 6.3v 2.7a Tab 1&2 6v .6A tab 3 and 4 130V DC .16A tabs 5&6

---