

---

Subject: Tweakin' agin

Posted by [Bill Epstein](#) on Sat, 22 Dec 2007 15:43:51 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Have a pretty nice integrated amp in for review and it intermittently distorts with lower dBs on one channel. The M sent me a set of new tubes. Trouble-shooting pointed to them but also could have been the crossover. I've meant to rebuild the Eminence 1.6ks for some time and this was a good excuse. Removed the components from the PCB and caulk'd em to a piece of plywood. That included a set of Edison Price Muisic Posts that had already proved thir worth along with Obbligato oils, a Jantzen 8.0 from PE and a honlin' big 15ga. Jantzen .6mH tweeter coil. No more connectors; all point-to-point. Crossover sounds great and definitely not the culprit. Now the amp is playing fine having been distorting on first try. That makes a tube problem doubtful. More likely an SMD, especially the Dact attenuator. Enjoying Laura Nyro while it stays working right. Have a Tweakin' Good Christmas, all!

---

---

Subject: Re: Tweakin' agin

Posted by [Wayne Parham](#) on Sun, 23 Dec 2007 21:12:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I hate those litle intermittent problems. Sometimes they're more irritating than if the whole thing went up in smoke.

---

---

Subject: Re: Problem seems to be gone

Posted by [Bill Epstein](#) on Wed, 26 Dec 2007 01:29:06 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Must have been the crossover which is a relief as returning the amp, getting another, etc really screws up the schedule. Good amp, too.

---