

---

Subject: Problem with Sansui 6060 receiver  
Posted by [Ross Rakoff](#) on Thu, 05 Jul 2007 17:57:00 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

I have a sansui 6060 receiver that sounds great and everything about it works, but the left side has the sound that sounds like embers burniong of the tip of a camp fire. This sound is present when volume is turned all the way down, on all input stages and when listed to on head phones. Does anyone know how to fix this problem?-Ross

---

Subject: Re: Problem with Sansui 6060 receiver  
Posted by [Wayne Parham](#) on Fri, 06 Jul 2007 02:56:19 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Perhaps it has a bad solder or possibly a bad resistor or transistor. You would think that a bad transistor would simply give a dead channel, but I've had 'em go bad like that. To me, when it happens, it sounds like there's arcing inside the substrate.

---

Subject: Re: Problem with Sansui 6060 receiver  
Posted by [Cheetah5386](#) on Sat, 21 Jul 2007 19:39:50 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Ross,Audio Karma has a Sansui Lovers forum. Lots of very knowledgeable Sansui fans there.Joe

---

Subject: Re: Problem with Sansui 6060 receiver  
Posted by [DAISYMAE](#) on Tue, 24 Jul 2007 11:23:08 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

I have a 6060 on the bench right now with the same problem. The problem was found to be the 2SC727 transistors in the driver Board. I replaced them with MPS A18 transistors and all is fine now. Frequently in 50 year old equipment transistors become noisy.