
Subject: Anyone have info on these?

Posted by [gofar99](#) on Sat, 11 Aug 2012 03:08:31 GMT

[View Forum Message](#) <> [Reply to Message](#)

Hi Everyone, I've had these around for some time and thought I might be able to put them to use but can't find any hard data on them. I ran the tests to determine the TS numbers and found that they are different. I suspect age has caused the change and one either has a more supple support structure or the other one that is more rigid. Ideas on getting them to match are welcome.

TS data

Speaker A / Speaker B

Fr 28.4 / 41.0

Qms 6.46 / 10.85

Qes 0.40 / 0.87

Qts 0.37 / 0.80

Re 5.8 / 5.8

They are 15 inch co-axials. They came from Lafayette Radio/Electronics sometime in the 60's or 70's. The only number is 21-47254W on the baskets.

LRE had some from several manufactures I believe incl Goodmans, Jenson, Utah. A web search didn't turn up anything in this size and configuration.

File Attachments

1) [IMG_0142 LRE Front.jpg](#), downloaded 2435 times

2) [IMG_0141 LRE Rear.jpg](#), downloaded 2477 times

Subject: Re: Anyone have info on these?

Posted by [gofar99](#) on Sat, 11 Aug 2012 15:37:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

Clearly from Utah as there are similar ones on ebay. Still no clue on what the "factory" parameters were. Nor any ideas on how to get them to match. I have considered that they may need to be broken in after sitting for years. Perhaps just feeding in a signal near the resonance points for a few days at low level. Ideas are always welcome.

Subject: Re: Anyone have info on these?

Posted by [Wayne Parham](#) on Sun, 12 Aug 2012 01:38:08 GMT

[View Forum Message](#) <> [Reply to Message](#)

Yes, I thought I recognized those too, but I'm not familiar with them.

But sadly, I think if the parameters are off like that, you'll probably need a recone. Old speakers sometimes have stretched or sagging suspensions, which can't be "massaged" back to life. I mean, they'll make sound, but they won't be right.

Subject: Re: Anyone have info on these?
Posted by [gofar99](#) on Sun, 12 Aug 2012 02:55:42 GMT
[View Forum Message](#) <> [Reply to Message](#)

Hi, yes, but probably not worth the cost. Right now they are buzzing away on an amp and signal generator. I'll see tomorrow if there have been any changes.
