

---

Subject: Turntable Rumble

Posted by [Tony](#) on Tue, 21 Sep 2004 19:12:14 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Got a rumble issue. It's not the motor, nor the record. Tables are properly grounded. What relation does speaker proximity have to rumble? Anyone with similar experiences? Solutions? Any help is great.

---

---

Subject: Re: Turntable Rumble

Posted by [Manualblock](#) on Tue, 21 Sep 2004 20:19:53 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Where is the TT sitting? If it is sitting on furniture and the furniture is solid and resting on the floor near the speaks could be an issue. Is it in a corner? Are the speaks on the floor and is the floor sprung with joists? Did the Rumble appear suddenly or did you change something. Is it an Direct Drive or suspended belt? Start with these issues first. J.R.

---

---

Subject: Re: Turntable Rumble

Posted by [DanR](#) on Tue, 16 Nov 2004 18:40:31 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Have you checked the platter thrust-bearing? Perhaps it is dry -- If you run the platter -- no disk -- and turn up the volume, do you hear more rumble than expected -- or previously heard?

---