

---

Subject: Pioneer PL-100 problems

Posted by [Troy James](#) on Sat, 08 Oct 2005 12:26:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi. I have the above turntable. It is about 20 years old and belt driven. I had the old belt (which had perished from lack of use) replaced recently at a Pioneer Shop. But the stroboscope will not line up and jumps erratically when adjusted. Any idea what the problem is and how I can solve it? Cheers

---

Subject: Re: Pioneer PL-100 problems

Posted by [Wayne Parham](#) on Sun, 09 Oct 2005 07:08:16 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Does the speed seem to fluctuate or just the strobe?

The service manual is available if you're interested.

---