Subject: Dual 1258 and Panasonic RD9090

Posted by Joshua Beecham on Mon, 06 Nov 2006 10:02:52 GMT

View Forum Message <> Reply to Message

I picked up an old Panasonic multiple play turntable. I have it plugged into a Sony receiver with a phono input. It plays fine, but its like the volume is hot. You barely turn up the volume knob and it's really loud and a little distorted. Anyone have any idea what the deal might be. As best I can tell the turntable had the original cartridge and diamond stylus. I replaced the stylus but the volume did the same thing with the new one. I would appreciate any thoughts. I'm rather new at this.Also, I am considering buying a Dual 1258 fully automatic/multiple play turntable in mint condition with an Ortifon cardridge. The people are asking about \$80 for it. Anyone know any history on that unit? Is that a good price? Any pitfalls I should watch out for.Thanks,Josh

Subject: Re: Dual 1258 and Panasonic RD9090
Posted by Wayne Parham on Tue, 14 Nov 2006 04:25:19 GMT
View Forum Message <> Reply to Message

Did you check the preamp input level? If it is set for moving coil and your cartridge has a moving magnet, that might do it. If the cartridge is ceramic, that would definitely do it.