

---

Subject: Yamaha YP-B2 Needle drops too far into record

Posted by [michael](#) on Sun, 17 Dec 2006 22:15:23 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The needle drops too far into the record. Where is the adjustment for this problem? Many thanks!!

---

---

Subject: Re: Yamaha YP-B2 Needle drops too far into record

Posted by [Wayne Parham](#) on Fri, 22 Dec 2006 15:12:27 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I've never looked at your turntable, but most auto-set/auto-return tone arm drops are damped by a hydraulic cylinder. If yours drops rapidly, the damper is probably bad.

---