

---

Subject: 41 280 tuner

Posted by [Sherry](#) on Mon, 18 Jul 2005 23:50:11 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I have a Philco 41 280. The tuner is not working after my recent move. How can I fix?

---

---

Subject: Re: 41 280 tuner

Posted by [Wayne Parham](#) on Tue, 19 Jul 2005 11:40:57 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Check the tubes and caps. The problem with old radios is usually the caps, but if it happened suddenly after a move, I would suspect the tubes. Try removing them and re-inserting them, one may just have a bad connection.

---