
Subject: Guinever done
Posted by [Forty2wo](#) on Tue, 01 Mar 2005 00:24:09 GMT
[View Forum Message](#) <> [Reply to Message](#)

Under going finel inspection by Jazz, chief wire tangler and all around big help...John
<http://img209.exs.cx/img209/8776/gov9tq.jpg>

Subject: Re: Guinever done
Posted by [Manualblock](#) on Tue, 01 Mar 2005 00:46:20 GMT
[View Forum Message](#) <> [Reply to Message](#)

John; Nice work; why are there two 5687's? And which rec tube did you use?

Subject: Many congrats
Posted by [colinhester](#) on Tue, 01 Mar 2005 01:10:47 GMT
[View Forum Message](#) <> [Reply to Message](#)

That's awesome. Looks like you beat me by a day. So, if that a high dielectric teflon coated cake pan?.....Colin

Subject: Nice....
Posted by [PakProtector](#) on Tue, 01 Mar 2005 01:48:16 GMT
[View Forum Message](#) <> [Reply to Message](#)

Love the cake-pan. Same questions, why two 5687 and what rectifier? did you perhaps parallel the two sections together?How does it sound? like you expected? better? comparable to the regulated version you heard in MD?regards,Douglas
