
Subject: pi 2 new tweeter upgrade help
Posted by [ImTweaked](#) on Tue, 24 May 2005 22:24:56 GMT
[View Forum Message](#) <> [Reply to Message](#)

when I remove the old tweeter what goes away with it? I see 2 parallel resistor that appears to be the candidadel think the coil has to do with the 10 inch woofer- TIA

Subject: Re: pi 2 new tweeter upgrade help
Posted by [Wayne Parham](#) on Wed, 25 May 2005 11:45:24 GMT
[View Forum Message](#) <> [Reply to Message](#)

resistor in parallel, right across the tweeter. The DX25 upgrade kit comes with a tweeter, a 10uF capacitor, a 16 ohm resistor and a pair of 0.110" spade lugs. Replace the existing 0.205" spade lugs with the new ones in the kit, and solder the 16 ohm resistor into the spade lugs along with the wires. Cut the silver colored wire on the tweeter line and splice in the 10uF capacitor. There should be no other components on the tweeter circuit. Leave the woofer line as it is.

Subject: Follow up questions (help Wayne -anyone?)
Posted by [ImTweaked](#) on Wed, 25 May 2005 12:02:57 GMT
[View Forum Message](#) <> [Reply to Message](#)

I noticed that on one side of my speaker there is a parallel pair of resistors (looks to be red-red-black-gold). This is the parallel resistors mentioned in above post. This resistors pair is wired from the woofer +ve to the negative. Is this correct? I am missing these resistors on the other speaker. which is correct? Basically I do not have a schematic of pi2 crossover with me and noticed the difference while changing to the new Vifa tweeter TIA

Subject: Re: Follow up questions (help Wayne -anyone?)
Posted by [Wayne Parham](#) on Wed, 25 May 2005 13:06:25 GMT
[View Forum Message](#) <> [Reply to Message](#)

resistors installed internally on the woofer line. Some people put 20 ohm resistors across speakers with piezos, so maybe someone decided to install yours internally. If so, remove them. Current models use a 0.5mH series coil in the woofer circuit, but older models don't have one. You can identify the driver by the label; Silver labels are the new ones. Models with silver label drivers

have the coil, older ones don't.

Subject: Thanks for the support and Clarification!
Posted by [ImTweaked](#) on Wed, 25 May 2005 13:49:50 GMT
[View Forum Message](#) <> [Reply to Message](#)

I will share my findings of the new Vifa when I get a chanceThanks

Subject: Re: Thanks for the support and Clarification!
Posted by [Wayne Parham](#) on Wed, 25 May 2005 13:51:37 GMT
[View Forum Message](#) <> [Reply to Message](#)

Thanks, Tony, I think you'll like them.
