Subject: Help with '45' problem?

Posted by Bill Epstein on Thu, 18 Aug 2005 08:29:53 GMT

View Forum Message <> Reply to Message

The DRD 45 sounds fine with FM Tuner and Fono. With CD it develops a fuzzy then raspy distortion that increases as the volume gets turned up.Same in both mono-blocks. Present with pre-amp and without.Can't drive them hard enough with Fono to tell but don't think so.97 dB speakers are really about 94 as they are 16 ohm.Changed the IC's: no difference.Changed the 45 tubes: no difference.6N1P drivers (Sovtek) are new.5AR4's are NOS Bugle Boys.CD has the highest output of the 3 sources followed closely by the Tuner. I can't hear it on the Tuner so can it simply be clipping?Some weird digital mis-match?