Subject: Re: TUbe amps in the greatest shape Posted by Wayne Parham on Sat, 20 Oct 2007 15:01:47 GMT View Forum Message <> Reply to Message

The voltage across the plate rises very high. It can exceed the maximum plate voltage rating in some cases. Certainly don't apply a signal to the preamp inputs with gain turned up if there is no load.