

---

Subject: Re: Turntable setup question

Posted by [Manualblock](#) on Sun, 25 Jan 2004 13:13:33 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hi Cameron; There will always be some inner groove distortion due to the limitations of tonearm geometry, but it should not be so apparent, I suspect you have an cartridge alignment problem. You did not state how you set-up your cartridge, how old it is, or what make and model as some are more critical of variations in azimuth, VTA and other factors. The Merrill set-up pamphlet is excellent for understanding these requirements and showing how to implement them. There is a copy floating around here somewhere if you are interested. J.R.

---