

---

Subject: Re: Pink Triangle LPT repair?

Posted by [audio origami](#) on Thu, 17 Feb 2005 18:11:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

hiive had a few of these with capacitor faults on the pcb ...causeing the fault you mention...i would think its not the motori have a DIY brushless motor on my sitejust email mej7

---