

---

Subject: timing mechanism

Posted by [moving in stereo](#) on Thu, 07 Apr 2005 01:47:49 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Hello,I have a Pioneer PL-2 belt drive turntable that is running fast on 33rpm (I assume on 45rpm as well). It is not chipmunk fast, but noticeable. For example a 5:10 song will only tak 4:40 to play so it seems to be off by about 10%Is this an easy Do It Yourself tweek/fix? If so any suggestions as to how?Many thanks.

---