

---

Subject: Re: Shure V 15Vxmr initial disappointment. Help needed!

Posted by [Manualblock](#) on Thu, 14 Jul 2005 13:29:20 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Have you checked to see if his pre-amp is properly loading the cartridge? That is a classic symptom of rolled off highs.

---