

---

Subject: Re: Turntable hum

Posted by [Manualblock](#) on Thu, 17 Nov 2005 21:29:21 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

O'Kay then it has to be easy. Either the cartridge is bad or the internal wiring of the tonearm has a problem. Before we check that though can you tell me what exactly you used to test the inputs of the pre-amp? Was it another low level source like a turntable?

---