

---

Subject: Re: my hitachi ht 6 turntable

Posted by [Wayne Parham](#) on Sun, 21 May 2006 04:30:02 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

The "spare wire" is probably a ground. Is it black?As for the lack of volume, you probably need a phono stage preamp. See the link below for more info:

Search results for "phono stage"

---