Subject: Re: my hitachi ht 6 turntable Posted by Wayne Parham on Sun, 21 May 2006 04:30:02 GMT View Forum Message <> Reply to Message

The "spare wire" is probably a ground. Is it black? As for the lack of volume, you probably need a phono stage preamp. See the link below for more info:

Search results for "phono stage"