

---

Subject: Re: Sony PS-LX295

Posted by [matt](#) on Sun, 07 Jan 2007 20:16:37 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I'm having the same problem with my PS-LX295, and am about to the point where I'm just going to try and salvage a transformer with 12 volt output and hardwire it. Don't know if this will work so don't take my word for it, I haven't tried it yet (haven't found the right voltage transformer).

---