

---

Subject: Re: Trying to figure out adjustment on an old JVC

Posted by [dvautier](#) on Tue, 09 Jan 2007 21:05:56 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Take the thing apart and study the mechanism. It probably needs a lub job anyway. If you are unable to figure it out in 2 or 3 hours, I would suggest looking for another TT.

---