

---

Subject: Re: Technics SL-23 buzz

Posted by [Auntie](#) on Thu, 01 Mar 2007 03:30:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Okay, I think I've figured out that it is a grounding issue...but here is a follow-up question:I have an old receiver (from craigslist) with phono jacks, so there are no worries here. However, this turntable is a gift to someone with a more modern stereo system. Without knowing what they have, can you tell me if I will definitely need a pre-amp connector in order to properly connect this turntable to their system?

---