Subject: Re: Technics SL BD22 Posted by Wayne Parham on Thu, 12 Mar 2009 22:49:54 GMT View Forum Message <> Reply to Message

Sounds like it might have blown the fuse. Are you sure it's wired for the right mains voltage level? Check that, and the fuse.

Page 1 of 1 ---- Generated from AudioRoundTable.com