Subject: Re: troubleshooting a tascam model 38 reel to reel Posted by Cyclotronguy on Tue, 26 Jul 2005 16:38:56 GMT View Forum Message <> Reply to Message

Or the capstain bearing is dry, galled, fretted and etc.

Page 1 of 1 ---- Generated from AudioRoundTable.com