

---

Subject: Re: Fault with sony tck-611 help  
Posted by [Wayne Parham](#) on Sat, 14 Jan 2006 17:38:12 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Sounds like a clutch is worn out.

---