

---

Subject: Re: Problem with Tascam 133

Posted by [Wayne Parham](#) on Fri, 16 Jun 2006 17:57:39 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Sounds like a tape head or connection to it. Examine the wires connected to the head.

---