

---

Subject: Re: Marantz PMD220 RCA line out problem  
Posted by [lthanlon](#) on Tue, 20 Jun 2006 22:25:01 GMT  
[View Forum Message](#) <> [Reply to Message](#)

---

Wayne, I'll check again when I get home tonight, but connector wear isn't likely to be the problem. Some of the RCA phone plugs in question were bought within the past week and haven't been used before. This is really odd. I'll take another look. Leigh

---