

---

Subject: Re: I-acoustics mtd 115a reliability

Posted by [Wayne Parham](#) on Thu, 23 Mar 2006 14:21:01 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

Thanks for reporting that. I've had a few - maybe 1 out of 500 - Eminence units with loose or misaligned dust caps. One had been glued only on about 20% of the edge of the cap, so most of it was loose and buzzed.

---