

---

Subject: Re: Other Drivers and stuff

Posted by [Bill Wassilak](#) on Thu, 01 Apr 2004 16:04:18 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

>>Do you have any references to test data handy? I was hoping for maybe some test results that quantified the onset of air-compressibility non-linearity distortion. EV does, EV discovered this on there MTL-4 high cabinets, the 4-10's that were driving the mid-bass horn were developing too much air-compression causing non-linearity in the throat section of the horn and causing the harmonic distortion to rise dramatically when driven near full power. Bill W.

---