
Subject: Re: starting construction on bass horn ?
Posted by [John Sheerin](#) on Mon, 28 Jun 2004 10:27:59 GMT
[View Forum Message](#) <> [Reply to Message](#)

Just another point to consider - the mechanical limit can be other things besides the voice coil crashing on the back plate:spider crashing on the top platevoice coil former coming out of the top of the gapsuspension getting torn upJohn
