

---

Subject: Re: Breaking ground loop hum caused by satellite dish...

Posted by [Wayne Parham](#) on Mon, 23 May 2005 15:39:43 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

If you're connecting using RF, use a 75 ohm to 300 ohm transformer. If you don't have a 300 ohm input, put two of 'em back to back.

---