

---

Subject: I solved the problem...

Posted by [Mr Vinyl](#) on Fri, 27 May 2005 14:02:32 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

I solved the problem using this device in between the dish ground and the house ground outside my house. See link.

<http://www.comm-omni.com/polyweb/iga90.htm>

---